



U.S. Department of Transportation

National Highway Traffic Safety Administration

Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

*** *** ***



Case Vehicle (A): 1998 Dodge Type: Caravan, 4-door van

Driver: 28-year-old female (30 weeks pregnant)

CDC: 12-FREW-1

Vehicle (B): 1990 Nissan Type: Pickup, 4x2 regular cab Driver: 53-year-old male

CDC: 99-0000-0

SITUATION

(Slides 1, 2) On a cloudy, dry day, case vehicle (A) was traveling west at a driver-estimated speed of 45 mph (72 kph) in the westbound lane of a two-lane asphalt road, in a rural area. Vehicle (B) was stopped facing south in a private drive that intersects with the two-lane road. As case vehicle (A) approached the private drive, vehicle (B) moved out into the intersecting westbound lane and began to make a left turn to travel east. The driver of case vehicle (A) was unable to avoid being struck in the right front by the left front of vehicle (B).

GENERAL VEHICLE DAMAGE AND ESTIMATED CRASH SEVERITIES

(Slide 3) The direct damage to case vehicle (A) began at the right-front bumper corner and extended 46 cm across the front bumper, resulting in a 32 percent vehicle overlap. The damage also extended 92 cm rearward along the right fender, with a maximum crush of 15 cm. (Slide 4) The maximum crush to the right-front bumper corner was 6 cm.

Using the WinSMASH accident-reconstruction program and c-values measured for (slides 5, 6 and 7) case vehicle (A), the following impact severity was calculated:

		Calculated Velocity Change - kph (mph)		
Vehicle	Variable	Total	Longitudinal	Latitudinal
Case Vehicle (A)	EBS	13 (8)	-12 (-8)	-2 (-1)

DESCRIPTION OF DAMAGE TO CASE VEHICLE (A)

Exterior

(Slides 8, 9 and 10) The right fender was crushed, the right turn indicator light was broken, and the right-front wheel was damaged. (Slides 11, 12) The right-front bumper corner was damaged, the right headlight was broken and there was damage to the right side of the hood. (Slide 14) There was no damage to the hood latch or hood hinges, and the rear edge of the hood was not elevated. Also, there was no damage to the windshield. In addition, the right wheelbase was reduced 6 cm. (Slide 13) There was no other damage to the right side and the doors were all operational.

(Slides 15, 16) There was no damage to the left side and no change in the left wheelbase. Both left-side doors were operational. (Slide 17) There was no damage to the rear of case vehicle (A).

Interior

(Slides 18, 19) This vehicle is equipped with steering-wheel and passenger frontal-impact airbags, which deployed during the frontal impact. (Slides 20, 21) There was no damage to the steering-wheel rim and no rotation of the steering column. (Slide 22) There was no damage to the left side of the upper or mid portions of the instrument panel, or the knee bolster. (Slide 23) There was no damage to the center instrument panel or the glove compartment. (Slides 24, 25 and 26) The distances between the lower steering-wheel rim and the seat cushion and the seat back were documented with the seat adjusted to the driver's reported pre crash position. The lower rim was 46 cm from the seatback, and the upper rim was 74 cm from the headrest. (Slides 27, 28 and 29) There was no interior damage and no intrusions were noted.

PREGNANT OCCUPANT KINEMATICS AND INJURIES

(Slide 30) The 5-ft, 8-in, 250-lb female driver was 30 weeks pregnant with twins. (Slides 31, 32, 33, 34, 35 and 36) She was wearing the available three-point belt, as evidenced by gray plastic marks on the shoulder-belt webbing from the plastic guide on the B-pillar, and the fact that the cover over the B-pillar was damaged. The steering-wheel frontal-impact airbag also deployed during this crash. (Slide 37) The shoulder-belt anchor point was adjusted to the lowest position on the B-pillar, and the driver reportedly had the seat adjusted to a rear-track position. She did not report any problems wearing the belt due to her pregnancy. She also had the steering-wheel in the full-up position due to her large pregnant abdomen, and she had her hands on the steering wheel at the 10 and 2 o-clock positions. She reportedly did not have time to apply the brakes before the impact.

During the impact, she continued forward and to the right relative to the vehicle interior into the belt restraints and the airbag. She complained of "stinging to her face" from contact by the deploying airbag, and pain in her right wrist. Radiology reports show no wrist fracture or dislocation.

After the crash, she complained of contractions, and was transported to a nearby hospital via ambulance. At the hospital, fetal heart tones were initially 120 to 140. Contractions subsided and she was discharged home within forty-eight hours of the crash. Fourteen days after the crash, she still complained of right wrist pain, but new x-rays reveal that there was no fracture or dislocation.

The following table (slide 38) and attached drawing summarize the information for the restrained driver.

NEONATAL OUTCOME

On May 11, 2000, at a gestational age of 35 weeks, the patient delivered a healthy 2.94 kg (6 lb, 7 oz) baby girl and a 2.39 kg (5 lb, 4 oz) baby boy by cesarean section. Apgar scores for both babies were 9 and 9 at 1 and 5 minutes, respectively.

Occupant: Driver
Restraints: 3-point belt worn; airbag deployed
Gestational age: 30 weeks

Age: 28 years Stature: 173 cm (5 ft, 8 in)

Sex: Female

Mass: 113 kg (250 lb)


			Injury Source	
Injury Description	A.I.S.	Definite	Probable	Possible
 No Injury				
Maximum A.I.S. Level	<u>o</u> .			
Injury Severity Score	<u>0</u>			
		<u>{</u>		·
At a gestational age of 35 weeks, the patient delivered a				
healthy 2.94 kg (6 lb, 7 oz) baby girl and a 2.39 kg (5 lb, 4 oz) baby boy. Apgar scores for both babies were 9 and				
9 at 1 and 5 minutes, respectively.				
			<u></u>	l

Duplicate columns 1-8 Module G I Format (from the previous card. 9 10 1	1 12	GENERAL INFORMATION	GI-1
Тіме		ENVIRONMENTAL CONDITIONS	
DATE OF COLLISION		CONSTRUCTION ZONE	
1 1	1 1		
	уу	(0) NO (1) YES (9) UNKNOWN	$\frac{\mathcal{O}}{33}$
HOUR OF COLLISION	<u> </u>	ROAD ALIGNMENT VERTICAL PLANE	
Location		(1) LEVEL	
		(2) CREST OF HILL (3) SLOPE (2%)	34
STATE:		(4) BOTTOM OF HILL (9) UNKNOWN	
STATE FIPS CODE	25 26	ROAD ALIGNMENT HORIZONTAL PLANE	
AREA		(1) STRAIGHT	1
(1) URBAN	2	(2) CURVE (3) T - SHAPED	35
(2) RURAL (9) UNKNOWN	27	(4) Y - SHAPED	35
(a) DIVINOVII		(7) OTHER:	
ENVIRONMENTAL CONDITIONS		SURFACE COVERING	
LIMITED-ACCESS HIGHWAY		(10) DRY	10
(0) NO (1) YES	0	(21) WATER - DAMP	36 37
(9) UNKNOWN	28	(22) WATER - WET (23) WATER - PUDDLED (29) WATER - AMOUNT UNKNOWN	
ROAD, TOTAL TRAFFIC LANES (FOR CASE VEHICLE)		(31) SNOW - LOOSE	
(1) 1-LANE		(32) SNOW - PACKED (39) SNOW - CONDITION UNKNOWN	
(2) 2-LANES	2		
(3) 3-LANES (4) 4 OR MORE LANES	-29	(41) ICE (51) SLUSH	
(5) DIVIDED, 4 OR MORE LANES (6) PARKING LOT/DRIVEWAY		(61) SPILLED GRAVEL (71) OTHER:	
(7) OTHER:(9) UNKNOWN		(99) UNKNOWN	
(b) Simulation		VISIBILITY LIMITATION	
INTERSECTING RD, TOTAL LANES		(FOR CASE VEHICLE)	
CHOOSE FROM ABOVE LIST, OR	10	(0) NONE (1) CLOUDY/DARK	
(8) NOT APPLICABLE	30	(2) FOG (3) SMOKE	38
		(4) WINDSHIELD CONDITION	
TYPE OF ROAD SURFACE		(5) GLARE (6) RAIN	
(1) ASPHALT	,	(7) OTHER: (8) ICE/SNOW	
(2) CONCRETE (3) GRAVEL	31	(9) UNKNOWN	
(4) MORE THAN ONE (CIRCLE EACH) (7) OTHER:		VISIBILITY OBSTRUCTION	
(9) UNKNOWN		(FOR CASE VEHICLE)	
DO 10 DEFECTS	I	(0) NONE (1) BUILDING	$\mid O \mid$
ROAD DEFECTS	1	(2) SIGN (3) VEGETATION <i>(E.G. BUSHES, SHRUBS)</i>	39
(0) NO (1) YES	6	(4) TREE (5) HILL OR CURVE IN ROAD	
(9) UNKNOWN	32	(6) VEHICLE IN TRANSPORT	
		(7) OTHER:(8) PARKED VEHICLE	
		(9) UNKNOWN	

		GENERAL INFORMATION GI-2
ENVIRONMENTAL CONDITIONS SPEED LIMIT (0) 5-45 km/h 5-25 mph (1) 46-55 30 (2) 56-60 35 (3) 61-70 40 (4) 71-79 45 (5) 80-85 50 (6) 86-90 55 (7) 91-105 60 (8) OVER 105 65 (9) UNKNOWN	4	MECHANICAL MALFUNCTION WAS THERE MENTION OF A MECHANICAL MALFUNCTION IN CASE VEHICLE (0) NO (1) YES (2) YES, DID NOT CONTRIBUTE TO ACCIDENT (9) UNKNOWN
PRECIPITATION	O 41	THE FOLLOWING SECTION SHOULD BE FILLED OUT IF A MECHANICAL MALFUNCTION IS RECOGNIZED OR SUSPECTED. CIRCLE ITEMS INVOLVED. SUPPORT ANY ITEMS CIRCLED WITH COMMENTS. BRAKE SYSTEM DRIVER CONTROLS EXHAUST SYSTEM POWER TRAIN STEERING SYSTEM FUEL SYSTEM SUSPENSION SYSTEM VISIBILITY ITEMS ELECTRICAL SYSTEM TIRES THROTTLE CONTROLS UNKNOWN OTHER: COMMENTS:
CROSSWIND (0) NONE - (1) LIGHT (2) STRONG (3) GUSTY & STRONG (9) UNKNOWN LIGHT CONDITIONS (1) DAYLIGHT (2) DAWN (3) DUSK (4) DARK, LIGHTED (5) DARK, UNLIGHTED (6) DARK, UNKNOWN IF LIGHTED (9) UNKNOWN	45	

	GENERAL INFORMATION	GI-3
<u>O</u> 47	HIGHEST POLICE INJURY SEVERITY CODE IN CRASH (NOT JUST CASE VEHICLE) (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY	
<u>O</u> 48	(5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (9) UNKNOWN	55
<u>O</u>	DRIVER IMPAIRMENT DRIVER ALCOHOL INVOLVEMENT (CASE VEHICLE) (0) NONE (1) YES (9) UNKNOWN/NOT REPORTED/ NO DRIVER	<u>O</u>
50	DRIVER ALCOHOL BAC (CASE VEHICLE) (80) NO TEST (90) CHEMICAL TESTS, NO RESULTS (95) AUTOPSY, NO RESULTS (99) UNKNOWN	<u>80</u> 57 58
51	WAS THERE MENTION OF DRIVER IMPAIRMENT FOR CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	<u>O</u> 59
<u>O</u> 52	LIST IMPAIRMENTS MENTION	NED:
53	Post - Crash Detail MANNER CASE VEHICLE LEFT SCENE	
<u>O</u>	(1) DRIVEN(2) TOWED DUE TO DAMAGE(3) TOWED, NOT DUE TO DAMAGE(4) TOWED, REASON UNKNOWN(9) UNKNOWN	2 000
	O 48 O 49 50 51 52	HIGHEST POLICE INJURY SEVERITY CODE IN CRASH (NOT JUST CASE VEHICLE) (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED. SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (9) UNKNOWN DRIVER IMPAIRMENT DRIVER ALCOHOL INVOLVEMENT (CASE VEHICLE) (0) NONE (1) YES (9) UNKNOWN/NOT REPORTED/ NO DRIVER DRIVER ALCOHOL BAC (CASE VEHICLE) (80) NO TEST (90) CHEMICAL TESTS, NO RESULTS (95) AUTOPSY, NO RESULTS (95) AUTOPSY, NO RESULTS (99) UNKNOWN WAS THERE MENTION OF DRIVER IMPAIRMENT FOR CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN LIST IMPAIRMENTS MENTION DRIVER LIST IMPAIRMENTS MENTION LIST IMPAIRMENTS MENTION DRIVER LIST IMPAIRMENTS MENTION DRIVER (1) DRIVEN (2) TOWED DUE TO DAMAGE (3) TOWED, NOT DUE TO DAMAGE (4) TOWED, REASON UNKNOWN

ACCIDENT DESCRIPTION: CASE LEHICLE (A) WAS TRAVELING	CASE VEHICLE (A): 1991 DODGE CAR AVAN
WEST AT A DRIVER-ESTIMATED SPEED OF 45 MPH	· · · · · · · · · · · · · · · · · · ·
(72 KPH). VEHICLE (B) WAS EXITING A PRIVATE	THIRD VEHICLE (C):
DRIVE PROM THE NORTH. VEHICLE (B) PULLED FROM	
STRUCK THE RIGHT FRONT OF CASE VEHICLE (A).	,
	NORTH



speed limit 45 mph (72 kph)

Duplicate columns 1-8 Module O V Format 0 4 from the previous card.	OTHER VEHICLE OV-1
MAKE: NISSAN MODEL: PICKUP 2x4	CARGO: UNKNOWN
VIN 13 N 6 S D 1 1 S 3	L C
MANUFAC/BODY CODE $ \frac{1}{30} $ $ \frac{8512}{34} $ MAKE/MODEL CODE $ \frac{1}{39} $ MODEL YEAR $ \frac{1}{39} $ $ \frac{9}{42} $ VEHICLE MASS (kg) $ \frac{0}{43} $ USAN TO SEPARATE REPORT WAS MADE, GIVE VEHICLE NUMBER NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN) $ \frac{1}{30} $ $ \frac{8512}{34} $ MAKE/MODEL CODE $ \frac{1}{39} $ $ \frac{9}{42} $ VEHICLE MASS (kg) $ \frac{0}{43} $ $ \frac{0}{43} $ NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)	VEHICLE TYPE PASSENGER VEHICLE (02) LARGE (03) LIMOUSINE (17) PICKUP CAR (20) UNKNOWN PASSENGER VEHICLE BODY (24) SUB-MINI (25) MINI (26) SUB-COMPACT (27) COMPACT (28) INTERMEDIATE (29) FULL MULTIPURPOSE PASSENGER VEHICLE (14) SMALL UTILITY (WHEELBASE LESS THAN 107*, E.G. JEEP, BRONCO) (15) LARGE UTILITY (WHEELBASE MORE THAN 107*, E.G. PANEL TRUCK, SUBURBAN) (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (17) PICKUP CAR WITH CANOPY/SHELL COVER (21) MOTOR HOME
TRAVELING SPEED (km/h) (000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	(22) PICKUP TRUCK WITH SLIDE-IN CAMPER (23) PICKUP CAR WITH SLIDE-IN CAMPER (31) CHASSIS-MOUNTED CAMPER TRUCK (11) VAN (12) PICKUP TRUCK (13) UNKNOWN LIGHT TRUCK (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (30) UNKNOWN TRUCK TYPE (31) CHASSIS-MOUNTED CAMPER (33) DELIVERY VAN (WALK-IN)
HIGHEST POLICE INJURY SEVERITY CODE FOR THIS VEHICLE (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (8) UNOCCUPIED VEHICLE (NOT APPLICABLE) (9) UNKNOWN	(34) STRAIGHT TRUCK (35) TRUCK-TRACTOR (BOBTAIL) (36) CHASSIS-CAB (37) UNKNOWN HEAVY TRUCK (38) TRACTOR & SEMI-TRAILER (SEMI) (39) TRUCK (OR SEMI) & FULL TRAILER(S) BUS (40) UNKNOWN BUS TYPE (41) SCHOOL BUS (42) INTERCITY BUS (BETWEEN CITIES) (43) TRANSIT BUS (INTRACITY) (44) STREETCAR (ON TRACKS) (68) TRAIN (CARS) (69) LOCOMOTIVE (ENGINE, SWITCHER)
	WHEELBASE (cm) (999) UNKNOWN 58 59 60

Duplicate columns 1-8 from the previous card. Module O V Format 0 2

OTHER VEHICLE

OV-2

ORIGINAL SPECIFICATIONS

Wheelbase

295 cm

Front Overhang

Curb Weight

Rear Overhang

Undeformed End Width (UEW)

Overall Length


Engine Displacement

Overall Width (OAW)

$$\int_{19}^{16} \frac{6}{5} \int_{21}^{18} cm$$

Engine: # of Cylinders

VEHICLE DAMAGE



FRONTAL CRASH OVERLAP

Round up for .5.98 = 98% or more Enter % overlap or "99" for missing or N/A. Direct Damage Length (DDL)

Front-End Overlap (Percent) =

Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEW)

Duplicate columns 1-8 Module V D Format 0 from the previous card.	4 12	VEHICLE DESCRIPTION	VD-1
MAKE: DODGE MODEL: CARAVAN 4-DOOR	VAN	CARGO: NONE	
VIN 2 B 4 F P 2	5 3 0	WR	29
MANUFAC/BODY CODE $\frac{2}{30}$ $\frac{2}{3}$ $\frac{1}{2}$	STOLE	N VEHICLE	
MAKE/MODEL CODE 3 22	38 (8) N		8 62
MODEL YEAR $\frac{1}{39} = \frac{9}{9}$	8 42		
VEHICLE MASS (kg) O 1 6 Q	48	STRUCTURE	2
ODOMETER (km) (ENTER 9'S IF UNKNOWN) (ENTER 8'S IF ELECTRONIC) 49	(2) L (3) II (4) B	ODY & FRAME INITIZED NTEGRAL-STUB FRAME ODY & PLATFORM FRAME E.G. <i>VW BUG)</i>	63
NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)	56 (7) C	ARTIALLY UNITIZED THER: INKNOWN	
TRAVELING SPEED (km/h)	<u>2</u>		
(000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	(0) N (1) A (2) M	MISSION ONE UTOMATIC IANUAL NKNOWN	64
VEHICLE TYPE			
PASSENGER VEHICLE (11) 2-DOOR HARDTOP (NO UPPER B-PILLAR)	24 SELECT	ION OF TRANSMISSION TOR LEVER	7
(12) 2-DOOR SEDAN OR COUPE (ANY UPPER B-PILLAR) (13) 4-DOOR HARDTOP	(2) C	LOOR ONSOLE OLUMN	3 65
(14) 4-DOOR SEDAN (15) STATION WAGON (16) CONVERTIBLE (18) OTHER PASS. VEH. : (19) PASSENGER VEHICLE, TYPE UNKNOWN	(7) 0	THER: NKNOWN	
MULTIPURPOSE PASSENGER VEHICLE	STEER	NG	
(21) SMALL UTILITY (E.G. JEEP, SCOUT, BRONCO) (22) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (23) VAN, SIZE UNKNOWN (24) VAN, SMALL (MINI) (25) VAN, LARGE (29) MPV, TYPE UNKNOWN (30) MOTOR HOME	(2) M	OWER ANUAL NKNOWN	66
TRUCK (31) PICKUP TRUCK, UNKNOWN	BRAKE		
(32) PICKUP TRUCK, SMALL (DOWNSIZED) (33) PICKUP TRUCK, LARGE	(2) M	OWER ANUAL NKNOWN	67
(99) UNKNOWN			

		VEHICLE DESCRIPTION VD-2
TYPE OF BRAKES (1) DRUM, ALL WHEELS (2) DISC, FRONT WHEELS (3) DISC, ALL WHEELS (9) UNKNOWN	<u>2</u>	WHEELBASE <i>(cm)</i> (999) Unknown 2 88 76 77 78
BRAKE ANTI-LOCK DEVICE (0) NONE INSTALLED (1) TWO-WHEEL (2) FOUR-WHEEL (7) EQUIPPED, UNKNOWN WHEELS (9) UNKNOWN AIR CONDITIONING IN VEHICLE (0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	<u>6</u> 9	PLASTIC ANTI-LACERATIVE INNER LAYER GLASS EQUIPPED (0) NONE (1) WINDSHIELD (2) WINDSHIELD AND SIDE (7) OTHER (9) UNKNOWN
TYPE OF DRIVE (1) REAR WHEEL (2) FRONT WHEEL (3) FOUR WHEEL (4) ALL WHEEL DRIVE (9) UNKNOWN DUAL REAR WHEELS (0) NO (1) YES (9) UNKNOWN ORIGINAL TYPE OF RESTRAINT SYSTEM (1) ACTIVE BELT (2) PASSIVE BELT (3) AIRBAG (4) KNEE BOLSTERS - (7) OTHER: (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	71	FIELD INVESTIGATOR INSTRUCTIONS: 1. INDICATE CRUSHED AREAS BY OUTLLINING NEW PERIMETER OF VEHICLE AND SHADING THE DAMAGED AREAS ON THE LARGE SKETCH ON PAGE VD-3. USE AS MANY SKETCHES AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE. 2. ENTER THE DIMENSIONS ON THE SKETCH(ES) MEASURED TO THE POINT OF MAXIMUM PENETRATION BY THE OBJECT(S) CONTACTED. USE THE EXAMPLES BELOW AS A GUIDE. 3. ENTER THE THREE DIMENSIONS TO THE CENTER OF THE WHEELS (WHEELBASE, FRONT AND REAR OVERHANGS) ON BOTH SIDES OF THE CAR. 4. ADD OTHER DIMENSIONS AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE. EXAMPLES:
EQUIPPED WITH ROLL BAR (0) NO (1) YES (9) UNKNOWN TYPE OF ROOF (0) NONE (1) SOLID (2) T-TOP CLOSED (3) T-TOP OPEN (4) SUN ROOF CLOSED (5) SUN ROOF OPEN (6) CONVERTIBLE CLOSED (7) CONVERTIBLE OPEN (8) OTHER: (9) UNKNOWN	<u>O</u> 74	FRONT OR REAR ROOF (REFERENCE TO TOP OF DOOR SILL OR WINDOW SILL) SIDE

Duplicate columns 1-8 from the previous card. Module V D Format 0 2 9 10 11 12

VEHICLE DESCRIPTION

VD-3

ORIGINAL SPECIFICATIONS

Wheelbase

Front Overhang

Curb Weight

Rear Overhang

$$\frac{0}{25}$$
 $\frac{9}{27}$ cm

Average Track Width
$$\frac{1}{13}$$
 $\frac{b}{b}$ $\frac{2}{15}$ cm

Undeformed End Width (UEW) 1 6 0 cm


Overall Length

Engine Displacement

Overall Width (OAW) 1 9 2 cm

Engine: # of Cylinders





FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A. 

Front-End Overlap (Percent) = DDL UEW

Duplicate columns 1-8 Module D // from the previous card.	A Format 0 2	Damage DA-1				
PRIMARY	CASE VEHICLE PRIMARY CDC	CONTACTED VEHICLE ASSOCIATED CDC				
EVENT NUMBER	13	_				
IMPACT SPEED (km/h)	999	<u>9 9 9</u> 35 36 37				
ESTIMATED BY	17	<u>/</u> 38				
CRUSH (cm)	0 0 6 8 19 20	9 9 9 39 40 41				
CDC #1	1 2 FREW 1 27	99.000.0 42 99.0000.0				
CDC #2	98.0000.00.34	99.000.0 49				
Duplicate columns 1-8 Module D A from the previous card.	N_Format _0 _3					
SECONDARY	CASE VEHICLE SECONDARY CDC	CONTACTED VEHICLE ASSOCIATED CDC				
EVENT NUMBER	13					
IMPACT SPEED (km/h)	14 15 16	35 36 37				
ESTIMATED BY	17	38				
CRUSH (cm)	18 19 20	39 40 41				
CDC #1	21	42				
CDC #2	28 34	49				
Codes	Codes					
EVENT NUMBER	EVENT NUMBER IMPACT SPEED ESTIMATOR CRUSH					
(8) NOT APPLICABLE (9) UNKNOWN IMPACT SPEED	(1) INVESTIGATOR (2) DRIVER (3) POLICE (4) "CRASH" PROGRAM	(998) NOT APPLICABLE (NO VEHICLE/DAMAGE) (999) UNKNOWN				
(998) NOT APPLICAB (999) UNKNOWN	(5) OTHER COMPUTER PROGRAM	CDC (9800000) NOT APPLICABLE (9900000) UNKNOWN				

Duplicate columns 1-8 from the previous card. Module D A Format 0 1 12

DAMAGE

DA-2

MAXIMUM SHEET METAL CRUSH

(cm) (999) UNKNOWN

RIGHT SIDE

REAR

LEFT SIDE

ROOF

OTHER

CHRONOLOGICAL SEQUENCE OF DAMAGE/INJURY PRODUCING CRASH EVENTS FOR CASE VEHICLE

NOTE: IF CHRONOLOGICAL ORDER IS UNKNOWN, EVENT ORDER IS OPTIONAL.

DO YOU KNOW THIS TABLE TO BE IN CHRONOLOGICAL ORDER?

(0) NO (1) YES

EVENT NUMBER	IMPACT LOCATION (1) ON ROADWAY (2) SHOULDERMEDIAN/GORE (3) ON ROADSIDE (4) OUTSIDE ROADSIDE RIGHT-OF-WAY (5) OTHER (6) OFF ROADWAY, LOC. UNK. (9) UNKNOWN	IMPACT CONFIGURATION FOR CODES, SEE TABLE ON PAGE DA-3.	OBJECT/VEHICLE CONTACTED FOR CODES, SEE TABLE ON PAGE DA-4.
- - # 1	32	1 1 34	12
#2	37	39	
#3	42		
#4	47	49	
#5	52		56
#6	57	 59	
#7	62	64	66

CODES FOR IMPACT CONFIGURATION

FRONT OF CASE VEHICLE

- (11) AND FRONT OF CONTACTED VEHICLE
- (13) AND SIDE OF CONTACTED VEHICLE
- (14) AND REAR OF CONTACTED VEHICLE
- (16) ENDSWIPED BY CONTACTED VEHICLE
- (17) AND OBJECT
- (19) AND UNKNOWN OTHER VEHICLE CONFIGURATION

LEFT SIDE OF CASE VEHICLE

- (21) AND <u>FRONT</u> OF CONTACTED VEHICLE (TYPE T) (22) AND <u>FRONT</u> OF CONTACTED VEHICLE (TYPE L)
- (23) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (24) AND REAR OF CONTACTED VEHICLE (TYPE T)
- (25) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (26) SIDESWIPED BY CONTACTED VEHICLE
- (27) AND OBJECT
- (29) AND UNKNOWN OTHER VEHICLE CONFIGURATION

REAR OF CASE VEHICLE

- (31) AND FRONT OF CONTACTED VEHICLE
- (33) AND SIDE OF CONTACTED VEHICLE
- (34) AND REAR OF CONTACTED VEHICLE
- (36) ENDSWIPED BY CONTACTED VEHICLE
- (37) AND OBJECT
- (39) AND <u>UNKNOWN</u> OTHER VEHICLE CONFIGURATION

RIGHT SIDE OF CASE VEHICLE

- (41) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (42) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (43) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (44) AND REAR OF CONTACTED VEHICLE (TYPE T)
- (45) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (46) SIDESWIPED BY CONTACTED VEHICLE
- (47) AND OBJECT
- (49) AND UNKNOWN OTHER VEHICLE CONFIGURATION

OTHER

- (57) VEHICLE TO OBJECT
- (58) VEHICLE TO VEHICLE
- (59) VEHICLE TO VEHICLE, CONFIGURATION UNKNOWN

ROLLOVER

- (61) LESS THAN 360°
- (62) 360° OR MORE
- (69) DETAILS UNKNOWN

UNKNOWN

(99) IMPACT TYPE UNKNOWN

CODES FOR VEHICLE/OBJECT CONTACTED

VEHICLE/OBJECT GROUPS

- NO OBJECT (00)
- (01) (39) PASSENGER VEHICLE & TRUCK
- (40) (69) OTHER VEHICLE
- (70) (76) PEDESTRIAN & ON-ROADWAY OBJECT
- (77) (97) OFF-ROADWAY OBJECT
- OTHER (DESCRIBE) (98)
- (99) **UNKNOWN**

PASSENGER VEHICLE

- (02) LARGE
- (03) LIMOUSINE
- (17) PICKUP
- (20) UNKNOWN PASSENGER VEHICLE BODY
- (24) SUB-MINI
- (25) MINI
- (26) SUB-COMPACT
- (27) COMPACT
- (28) INTERMEDIATE
- (29) FULL

SIZE

SUB-MINI	< 2286 mm (< 90")
MINI	2286 - 2412 mm (90" - 94.9")
SUB-COMPACT	2413 - 2539 mm (95" - 99.9")
COMPACT	2540 - 2666 mm (100" - 104.9")
INTERMEDIATE	2667 - 2793 mm (105" - 109.9")
FULL	2794 - 2920 mm (110" - 114.9")
LARGE	2921 - 3174 mm (115" - 124.9")
LIMOUSINE	> 3175 mm (> 125")

WHEELBASE

MULTIPURPOSE PASSENGER VEHICLE

- (11) SMALL VAN (MINI)
- (12) PICKUP
- (14) SMALL UTILITY (WHEELBASE LESS THAN 107°, E.G. JEEP, BRONCO)
- (15) LARGE UTILITY (WHEELBASE MORE THAN 107°, E.G. PANEL TRUCK, SUBURBAN)
- (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
- (17) PICKUP CAR WITH CANOPY/SHELL COVER
- (21) MOTOR HOME
- (22) PICKUP TRUCK WITH SLIDE-IN CAMPER
- (23) PICKUP CAR WITH SLIDE-IN CAMPER
- (31) CHASSIS-MOUNTED CAMPER

TRUCK

- (11) SMALL VAN (E.G. ECONOLINE)
- (12) PICKUP TRUCK
- (13) UNKNOWN LIGHT TRUCK
- (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN)
- (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
- (22) PICKUP TRUCK WITH SLIDE-IN CAMPER
- (30) UNKNOWN TRUCK TYPE
- (31) CHASSIS-MOUNTED CAMPER
- (33) DELIVERY VAN (WALK-IN) (34) STRAIGHT TRUCK
- (35) TRUCK-TRACTOR (BOBTAIL)
- (36) CHASSIS-CAB
- (37) UNKNOWN HEAVY TRUCK
- (38) TRACTOR & SEMI-TRAILER (SEMI)
- (39) TRUCK (OR SEMI) & FULL TRAILER(S)

BUS

- (40) UNKNOWN BUS TYPE
- (41) SCHOOL BUS
- (42) INTERCITY BUS (BETWEEN CITIES)
- (43) TRANSIT BUS (INTRACITY)
- (44) STREETCAR (ON TRACKS)

MOTORCYCLE

- (50) UNKNOWN MOTORCYCLE TYPE
- (51) 1 75 cc
- (52) 76 125 cc
- (53) 126 250 cc
- (54) 251 500 cc
- (55) 501 750 cc
- (56) 751 cc +
- (57) 3-WHEELS (OR WITH SIDECAR)

SPECIAL PURPOSE VEHICLE

- (60) UNKNOWN/OTHER SPECIAL VEHICLE (DESCRIBE)
- (61) SNOWMOBILE
- (62) ATV (ALL TERRAIN VEHICLE)
- (63) AMPHIBIOUS VEHICLE
- (64) FARM VEHICLE
- (65) CONSTRUCTION VEHICLE
- (66) TRAILER, PRIVATE (CAMPER)
- (67) TRAILER, COMMERCIAL (CARGO)
- (68) TRAIN (CARS)
- (69) LOCOMOTIVE (ENGINE, SWITCHER)

OBJECT

- (70) PEDESTRIAN
- (71) BICYCLIST, OTHER PEDALCYCLIST
- (72) PEDESTRIAN CONVEYANCE (E.G. PERSON RIDING ANIMAL, CART)
- (73) LARGE ANIMAL
- (74) FALLEN OBJECT (E.G. OBJECT DISLODGED FROM OTHER VEHICLE, FALLEN TREE, ROCKS)
- (75) ROCKS
- (76) CONSTRUCTION EQUIPMENT (EXCLUDING (65))
- (77) SIGN POST, UTILITY POLE, TREE
- (78) DITCH
- (79) EMBANKMENT, SNOWBANK, RR TRACKS RR X
- (80) GROUND (ROLLOVER ONLY)
- (81) CURB (DAMAGE PRODUCING IMPACTS ONLY)
- (82) CULVERT
- (83) FENCE
- (84) HYDRANT, SHORT POST, STUMP
- (85) SMALL POST/TREE, RURAL MAIL BOX, MILE MARKER, DELINEATOR
- (86) BUILDING
- (87) PIER, PILLAR, BRIDGE SUPPORT
- (88) ABUTMENT, RETAINING WALL
- (89) BRIDGE RAIL
- (90) GUARD RAIL, LEADING SECTION

- (91) GUARD RAIL, MIDDLE OR UNKNOWN
 (92) GUARD RAIL, TRAILING SECTION
 (93) GUARD POST (TIMBER, METAL, CONCRETE)
- (94) CABLE, FENCE BARRIER
- (95) CONCRETE BARRIER (MEDIAN) (96) IMPACT ATTENUATOR
- (97) BREAKAWAY FEATURES

Module <u>C</u> <u>R</u> Format <u>0</u> <u>1</u> 12 CRASH RECONSTRUCTION CR-1 Duplicate columns 1-8 from the previous card. for ΔV CASE VEHICLE PRIMARY IMPACT CASE VEHICLE SECONDARY IMPACT CASE CONTACTED CASE CONTACTED **VEHICLE VEHICLE VEHICLE VEHICLE EVENT NUMBER** 47 ΔV (km/h) TOTAL 66 67 68 LONGITUDINAL* 54 72 LATERAL* 58 76 NOTE: THESE AV COMPONENTS MUST INCLUDE SIGN. EXAMPLES: 10 km/h = ± 0 1 0 $-7 \, \text{km/h} = -0.07$ **ENERGY DISSIPATED BY** CRUSH (kg) 28 62 77 80 RECONSTRUCTION (01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL 63 64 (21) RECONSTRUCTED, LOW **CONFIDENCE LEVEL** (22) RECONSTRUCTED, MODERATE **CONFIDENCE LEVEL** (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL NOT RECONSTRUCTED BECAUSE (02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ **OVERRIDE** (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT (10) OTHER: (11) AT LEAST ONE VEHICLE **BEYOND SCOPE** (12) OTHER VEHICLE NOT **INSPECTED** MODE (1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC 65 (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED **COMPUTER PROGRAM** SPECIFY:_

Duplicate columns 1-8 Module C From the previous card. 9 10	R Format 0 2		SH RECONSTRUC OF EBS	TION CR-2
	CASE VEHICLE F	PRIMARY IMPACT	CASE VEHICLE SE	CONDARY IMPACT
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE
EVENT NUMBER	13	, <u>E</u> ,	47	VEHICLE
EBS (km/h) TOTAL	0 13	9-	48 49 50	66 57 66
LONGITUDINAL*	<u>-012</u>	9	51 54	60 72
LATERAL*	-002	9—	·	
*NOTE: THESE EBS COMPONENTS MUST INCLUDE SIGN.	21 24	39 42	56 58	73 76
EXAMPLES: 10 lands = ± <u>0</u> 1 <u>0</u> -7 lands = <u>: 0 0 7</u>				
ENERGY DISSIPATED BY CRUSH (4)	0 106	9		77 - 80
RECONSTRUCTION				
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	<u>2</u> 1			
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL	29 30		63 64	
(22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL				
(23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL				
NOT RECONSTRUCTED BECAUSE				
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/				
OVERRIDE (04) ROLLOVER		÷		
(05) VAULTING (06) OTHER TRAVEL IN MORE				
THAN ONE PLANE (07) NON-HORIZONTAL FORCE				
(08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT				
(10) OTHER:				
BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED				
MODE				
(1) CDC ONLY (2) CDC & DETAILED DAMAGE	2			
(3) TRAJECTORY & CDC (4) TRAJECTORY & CDC &	31		65	
DETAILED DAMAGE (5) NOT RECONSTRUCTED				
COMPUTER PROGRAM SPECIFY: WIN SCHOOL				

CRASH RECONSTRUCTION Module C R Format 0 3 Duplicate columns 1-8 CR-3 from the previous card. 10 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS NOTES: CASE VEHICLE 2. MEASURE C_1 TO C_6 FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS. LOCATOR 3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG. 4. USE THE CENTER OF THE WHEELBASE AS THE CG. Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axie for side impacts. Specific Impact No. Location of Direct Damage Location of Field L BC to BC BEGINS AT RIGHT-FRONT Bumper corner 46-cm C6 **C5** DL UDL PLANE: (1) Bumper (2) Above Bumper (3) SM (4) Above Sill (5) Other (9) Unknown **CRUSH PROFILE IN CENTIMETERS** NOTE: Each line in the table below is a separate record (card). Duplicate columns 1 - 12 for each completed line. Direct Damage Specific Plane of Impact Length (DDL) Impact Field C₁ C_2 Max C_5 C_3 C4 C_{6} ±D Number C-Measur. Crush 46 C1(6) 160 0 0 Ø 0 6 57 1 046 000 000 000 003 006 160 006 やいろつ 13 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45

2

Duplicate columns 1-8	
from the previous card.	

Module <u>C</u> <u>R</u> Format <u>0</u> <u>4</u> 11 12

CRASH RECONSTRUCTION

CR-4

NOTES:

- 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS.
- 2. MEASURE C_1 TO C_6 FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS.

OTHER VEHICLE

LOCATOR

- 3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG.
- 4. USE THE CENTER OF THE WHEELBASE AS THE CG.

Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts.


Specific Impact No.	Location of Direct Damage	Location of Field L



PLANE:

- (1) Bumper
- (2) Above Bumper
- (3) Sill
- (4) Above Sill

(5) Other_ (9) Unknown



DL

UDL

CRUSH PROFILE IN CENTIMETERS

	NOTE: Each	line in the tab		separate rec			olicate colu	umns 1 - 1	2 for each	complete	d line.
Specific Impact Number	Plane of Impact C-Measur.	Direct Length (DDL)	Damage Max Crush	Field L	C ₁	C ₂	C ₃	C ₄	C ₅	C ₆	±D
_											
1											
13	14	15 16 17	18 19 20	21 22 23	24 25 26	27 28 29	30 31 32	33 34 35	36 37 38	39 40 41	42 43 44 45
2											

	T Format 0 1	WHEELS AND TIRES WT-
WHEELSDAMAGED (0) NO (1) YES (9) UNKNOWN	LF C	SIZE (NOT DOT CODE. IF UNKNOWN, USE 9'S) LF
TIRE TREAD TYPE (1) REGULAR (2) SNOW (3) SLICKS (4) ALL WEATHER (MS) (7) OTHER: (9) UNKNOWN	LF <u>4</u> RF <u>4</u> RR <u>4</u> LR <u>4</u>	LR
CARCASS CONSTRUCTION (1) BIAS (2) BELTED BIAS (3) RADIAL (4) ELLIPTICAL (5) HI PRESSURE SPARE (6) SPACE SAVER SPARE (7) OTHER: (9) UNKNOWN	LF 3/3 RF 3/4	
F VEHICLE IS EQUIPPED WITH DUAL WHEELS, COMPLETE FOR OUTER WHEE ND MAKE NOTES ON INNER WHEELS. WOTES:	LS	

Duplicate columns 1-8 Module F from the previous card.	T Format 0	1 12	FUEL AND FUEL TANKS	FT-1
TYPE OF PROPULSIVE FUEL (1) GASOLINE (2) DIESEL OIL (3) LPG (4) ELECTRIC (7) OTHER: (9) UNKNOWN		13	AUXILIARY TANK TYPE (1) OEM TANK (2) AFTER MARKET TANK (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	<u>8</u>
MAIN TANK LOCATION		322 14	AUXILIARY TANK LOCATION	<u>888</u>
MAIN FILLER CAP LOCATION		$\frac{1}{17} \frac{13}{19}$	AUXILIARY FILLER CAP LOCATION	<u>888</u>
MAIN TANK MATERIAL	_L	20	AUXILIARY TANK MATERIAL	<u>8</u> − 28
т,	ANK AND F	ILLER C	AP LOCATION CODES	
	FIRST DIGIT	T (LONGITI	UDINAL)	
	(2) IN K (3) BET (4) FOR	WEEN KIC WARD OF APPLICAE	K-UP & COWL	
	SECOND DI	GIT (LATE	RAL)	
		T OF FRAM	TE CONTERED	

TANK MATERIAL CODES

- (1) STEEL
- (2) ALUMINUM (3) PLASTIC (7) OTHER

- (8) NOT APPLICABLE (NOT EQUIPPED)
 (9) UNKNOWN

(2) WITHIN FRAME OR CENTERED

(2) WITHIN FRAME OR CENTERED
(3) ABOVE FRAME

(8) NOT APPLICABLE (NOT EQUIPPED)
(9) UNKNOWN

(4) DUAL, RIGHT & LEFT TANKS (8) NOT APPLICABLE (NOT EQUIPPED)

(3) RIGHT OF FRAME

(9) UNKNOWN THIRD DIGIT (VERTICAL) (1) BELOW FRAME

Duplicate colum from the previou		F L Format 0			FUEL LEAK	AGE FL-1
	(0) N	EL LEAKAGE RE O KNOWN LEAKAG ES <i>COMPLETE PA</i>		CRASH EVENT	<u>O</u>	
	1	11	111	IV	V	
LEAK NUMBER	LEAKING COMPONENT	COMPONENT SOURCE	TYPE OF DAMAGE	SEVERITY OF DAMAGE	LOCATION OF LEAK	EVENT NUMBER
#1	14 15					21
#2	22 23		<u> </u>			29
#3	30 31	-	_			37
#4	38 39	_				45
#5	46 47					53

LEAKING COMPONENT

TANK AREA

- (11) MAIN FUEL TANK (INCLUDING VAPOR RECOVERY DOME)
- (12) AUXILIARY FUEL TANK
- (13) MAIN TANK FILLER TUBE
- (14) MAIN TANK CAP (GAS CAP) (15) AUXILIARY TANK FILLER TUBE
- (16) AUXILIARY TANK CAP (GAS CAP)
- (19) TANK AREA, DETAILS UNKNOWN

DELIVERY SYSTEM

- (21) FUEL FEED LINE (MAIN TANK TO FUEL PUMP)
- (22) FUEL FEED LINE (AUXILIARY TANK TO FUEL PUMP)
- (23) FUEL RETURN LINE (FUEL PUMP TO TANK)
- (24) INLINE FUEL FILTER
- (25) FUEL LINE (PUMP TO
- CARBURETOR OR INJECTOR PUMP) (26) CARBURETOR TO INJECTOR PUMP
- (27) FUEL PUMP
- (29) DELIVERY SYSTEM, DETAILS UNKNOWN

EVAPORATIVE EMISSION CONTROL SYSTEM

- (31) ATMOSPHERIC VENT PIPE (NON-EEC EQUIPPED)
- (32) EEC PIPE (VAPOR CANISTER TO CARBURETOR)

EEC SYSTEM (CONTINUED)

- (33) VAPOR RECOVERY HOSES (CANISTER TO CARBURETOR)
- (34) LIQUID-VAPOR SEPARATOR (UNLESS PART OF TANK)
- (35) CANISTER
- (39) EEC SYSTEM, DETAILS UNKNOWN
- (49) ENGINE COMPARTMENT, COMPONENT UNKNOWN
- (99) COMPONENT UNKNOWN

I COMPONENT SOURCE

- (1) OEM
- (2) AFTER MARKET
- (9) UNKNOWN

III TYPE OF DAMAGE

- (1) DENTED/CRUSHED
- (2) PUNCTURED
- (3) RUPTURED
- (4) SEVERED/GROSS TEARS
- (5) DISCONNECTED/DEFEATED
- (9) UNKNOWN

IV SEVERITY OF DAMAGE

- (1) MINOR
- (2) MODERATE
- (3) SEVERE
- (4) DISCONNECTED/DEFEATED
- (9) UNKNOWN

V LOCATION OF LEAK

FIRST DIGIT (LONGITUDINAL LOCATION)

- (1) F, FORWARD OF COWL
- (2) P, BETWEEN COWL & **REAR BULKHEAD**
- (3) B, BEHIND REAR BULKHEAD
- (4) Y, F, & P
- (5) Z, P, & B
- (6) D, DISTRIBUTED (F, P & B)
- (9) UNKNOWN

SECOND DIGIT (LATERAL LOCATION)

- (1) L, LEFT
- (2) C, CENTER
- (3) R, RIGHT
- (4) Y, LEFT CENTER (L & C)
- (5) Z, RIGHT CENTER (R & C)
- (6) D, DISTRIBUTED (F, P & B)
- (9) UNKNOWN

Duplicate columns 1-8 Module F R Format 0 11 11 11 11 11 11 11 11 11 11 11 11 1	1 12	FIRE	FR-1
WAS THERE FIRE IN (0) NO <u>SKIP</u> PAG (1) YES <u>COMPLE</u>	GE.	CASE VEHICLE?	
DID FIRE START IN CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	14	SEVERITY OF FIRE DAMAGE (1) MINOR (2) MODERATE (3) SEVERE (9) UNKNOWN	16
FLAME PROPOGATION RATE (1) RAPID/EXPLOSIVE (2) SLOW/MODERATE (9) UNKNOWN	15	DID AN INJURY TO CASE VEHICLE OCCUPANT RESULT FROM FIRE IN OR ON CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	17

PROVIDE NOTES IF FIRE OCCURRED.

Duplicate columns 1-8 from the previous card.	Module <u> </u>	<u>D</u> Format	0 1	Exterior Damage	ED-1
HOOD PERFORMA FOR THE FOLLOWING (0) NO		DES:		STEERING COL FLEXIBLE COUPLING FLEXIBLE COUPLING TYPE (0) NONE (1) FLEXIBLE MATERIAL (2) POT	9 26
(1) YES (8) NOT APPLICA (9) UNKNOWN HOOD LATCH(ES)-	ABLE	-RELEASED	٥	(3) SINGLE U-JOINT (4) DOUBLE U-JOINT (5) FLEXIBLE CABLE (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OTHER: (8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN, IF EQUIPPED	
		-DAMAGED	Ö	(9) GINNIOWIN, IF EQUIPPED	
		-JAMMED	13 0 14 8 15	COUPLINGDAMAGED (USE CODES FROM HOOD PERFORMANCE) -SEPARATED	
HOOD HINGES-	-LEFT,	DAMAGED	$\frac{\mathcal{O}}{16}$	(COMPLETE)	28
	-LEFT,	SEPARATED (COMPLETE)	<u>&</u>		
	-RIGHT,	DAMAGED	0	ENG COMPART TELESCOPING UNIT	
	-RIGHT,	SEPARATED (COMPLETE)	17 O 18 S 19	TYPE OF UNIT (00) NONE INSTALLED (01) - (07) SEE UNITS ON PAGE ED-2 (88) NOT COLLECTED	8 8
HOOD REMAINED ON	VEHICLE		20	(97) OTHER: (98) EQUIPPED, TYPE UNKNOWN (99) UNKNOWN IF EQUIPPED	29 30
REAR EDGE OF HOOD)-	-ELEVATED	Q	ORIGINAL LENGTH (mm)	
-cor	NTACTED	WINDSHIELD	₹ <u>8</u>	F (OR H):	
-PEN	NETRATED	WINDSHIELD	8 23	TELESCOPED LENGTH (mm) G:	
HOOD LATCH LOCATIO	ON				
(1) FRONT OF VEH (2) COWL AREA (3) SIDE (8) NOT APPLICAB			<u></u>	DIFFERENCE <i>(mm)</i> F <i>(OR H)</i> - G	
(9) UNKNOWN				(IF LESS THAN 15mm, ENTER *000*.)	
ENGINE OR TRANSM SEPARATION (COMPL		Mount		(888) NOT COLLECTED (991) NOT MEASURED/NO COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED	8 8 8
(0) NO (1) YES (9) UNKNOWN			<u>O</u> <u>25</u>	(997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	

		EXTERIOR DAMAGE	ED-2
LEFT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>8</u>	LEFT DOORS HOW DID DOORS OPEN DURING COLLISION?	
LEFT PILLARS PILLARS SEPARATED COMPLETELY - USE CODES: (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN		USE CODES: (0) DOOR DID NOT OPEN OPENED BECAUSE OF (1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN	
-A-PILLAR, UPPER	35	(8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	_
LOWER	<u>Ø</u>	-FRONT -REAR	0 43
-B-PILLAR, UPPER	<u>O</u> 37		44
LOWER	<u></u>	DOORS JAMMED CLOSED- USE CODES: (0) NO	
-C-PILLAR, UPPER	$\frac{O}{39}$	(1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	<i>(</i> 2)
LOWER	<u>0</u>	-FRONT -REAR	0 45 0
-D-PILLAR, UPPER	$\frac{0}{41}$	TILAN	46
LOWER	<u>O</u>		

		EXTERIOR DAMAGE	ED-3
		OTHER REAR DAMAGE	
REAR DOOR REAR DOOR TYPE (0) NO DOOR (INCLUDES PICKUPS) (1) HATCHBACK (2) ONE-WAY TAILGATE (3) TWO-WAY TAILGATE (4) CLAMSHELL/DISAPPEARING TAILGATE (5) SINGLE DOOR (6) DOUBLE DOOR	2 47	WAS PARTITION TO LUGGAGE AREA DAMAGED DURING COLLISION? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN SPARE TIRE	<u>8</u> 50
(9) UNKNOWN Hatchback One-way		(0) NO SPARE TIRE (1) NOT ATTACHED BEFORE COLLISION (2) ATTACHED, NOT SEPARATED IN COLLISION (3) ATTACHED, SEPARATED DUE TO COLLISION (8) NOT COLLECTED (9) UNKNOWN	51
Two-way Clamshell Single door		TRAILER HITCH TYPE (0) NO HITCH BALL-AND-SOCKET TYPES (1) TEMPORARY FRAMEWORK (E.G. RENTAL CLAMP-ON) (2) BUMPER-MOUNT ONLY (E.G. LIGHT TRUCK) (3) BUMPER-AND-FRAME (BUT NON-EQUALIZING) (4) LOAD EQUALIZING	<u>O</u> 52
HOW DID DOOR OPEN DURING COLLISION? (0) DOOR DID NOT OPEN OPENED BECAUSE OF (1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	Q 48	(5) RING-AND-PINTLE (6) FIFTH-WHEEL (INCL. P/U) (7) OTHER (E.G. CLEVIS-AND-PIN) (8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN IF EQUIPPED TRAILER TYPE (AT TIME OF COLLISION) (0) NO TRAILER (1) TRAVEL-TRAILER/CAMPER (2) MOBILE HOME (3) BOAT/SNOWMOBILE/ATV TRAILER (4) UTILITY TRAILER (5) TOWED CAR (7) OTHER: (8) TRAILER, TYPE UNKNOWN (9) UNKNOWN	<u>O</u> 53
(0) NO (1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	<u>O</u>		

		Exterior Damage	ED-4
RIGHT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>8</u>	RIGHT DOORS HOW DID DOORS OPEN DURING COLLISION? USE CODES:	
RIGHT PILLARS PILLARS SEPARATED COMPLETELY - USE CODES: (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN		(00) DOOR DID NOT OPEN OPENED BECAUSE OF (01) HINGE AREA SEPARATION (02) DOOR-LATCH SEPARATION (03) LATCH-STRIKER SEPARATION (04) STRIKER-PILLAR SEPARATION (05) BODY DISTORTION (06) COMBINATION OF ABOVE (CIRCLE EACH) (07) OPENED, REASON UNKNOWN (11) VAN RIGHT-REAR DOOR OPENED (ANY MECHANISM)	
-A-PILLAR, UPPER	<u>O</u> 55	(98) NOT APPLICABLE <i>(NO DOOR)</i> (99) UNKNOWN	
LOWER	<u>Ø</u>	-FRONT -REAR	
-B-PILLAR, UPPER	<u>©</u> 57		65 66
LOWER	<u>O</u> 58	DOORS JAMMED CLOSED- USE CODES: (0) NO (1) YES	
-C-PILLAR, UPPER	$\frac{\mathcal{O}}{59}$	(8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	0
- LOWER	$\frac{\mathcal{O}}{60}$	-FRONT	67
-D-PILLAR, UPPER	$\frac{\bigcirc}{61}$	-REAR	<u>O</u> 68
LOWER	62	VAN REAR DOOR TYPE (0) VAN, NO REAR DOOR (1) TRACK (SLIDING) - RIGHT SIDE (2) SINGLE-HINGED - RIGHT SIDE (3) DOUBLE-HINGED - RIGHT SIDE (4) TRACK (SLIDING) - RIGHT & LEFT SIDE (5) SINGLE-HINGED - RIGHT & LEFT SIDE (6) DOUBLE-HINGED - RIGHT & LEFT SIDE (7) TRACK AND HINGED COMBINATION (8) NOT APPLICABLE (NOT A VAN) (9) UNKNOWN	9


		EXTERIOR DAMAGE	ED-5
WINDSHIELD DAMAGE		WINDSHIELD MARK ON CASE VEHICLE:	
WINDSHIELD CRACKED (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	70	SAFE GUARD DOT- GG M	
WINDSHIELD BROKEN (PLASTIC INTERLAYER TORN) (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	71	ASI-	
CRACKED OR BROKEN BY OCCUPANT CONTACT (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN EXTENT OF BOND SEPARATION (0) NONE (1) 1 - 20% (2) 21 - 40 (3) 41 - 60 (4) 61 - 80 (5) 81 - 99 (6) TOTAL (7) SEPARATED, AMOUNT UNKNOWN (8) NOT APPLICABLE (9) UNKNOWN	8 72 ○ 73	WINDSHIELD CODE (97) DESCRIBED BUT NOT CODED (98) NOT APPLICABLE (NO WINDSHIELD) (99) UNKNOWN ROOF DID T-ROOF/SUN ROOF OPEN DURING COLLISION? (0) NO (1) YES (8) NOT APPLICABLE (NOT A T-ROOF OR SUN ROOF) (9) UNKNOWN	97/74 75 74 75
LOCATE AREA OF WINDSHIELD INT & HORIZONTAL) ON THIS DIAGRA	EREST OF	R DAMAGE WITH DIMENSIONS (VERTICAL WINDSHIELD AS VIEWED FROM INSIDE.	
L	Ç	-	 R


Duplicate columns 1-8 Module S C Format 0 from the previous card. 9 10 11		STEERING WHEEL AND COLUMN	SC-1
STEERING WHEEL	1	STEERING WHEEL POSITION AT TIME OF COLLISION	
STEERING WHEEL RIM DAMAGE (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	13	IN WHAT O'CLOCK POSITION WAS THE NORMAL TOP OF THE WHEEL POINTED WHEN THE COLLISION OCCURRED? EXAMPLES O'CLOCK = 1 2 O'CLOCK = 0 2	
NUMBER OF STEERING WHEEL SPOKES (9) UNKNOWN	3_14	(NORMAL STRAIGHT AHEAD) (99) UNKNOWN	
STEERING WHL SPOKE DAMAGE (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	<u>O</u> 15	STEERING WHEEL ENERGY ABSORBING DEVICE (1) EXAMPLES: BARRACUDA, 70 - 74 CHALLENGER, 70 - 74 CAPRI, 71 - 77	
STEERING COLUMN OPTIONS		(2) EXAMPLES: OMNI, 78 - HORIZON, 78 -	
TILT FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED, UNK POSITION (2) UP (3) MIDDLE (4) LOWER (9) UNKNOWN IF EQUIPPED	<u>2</u>	TYPE OF DEVICE (0) NONE (1) CONVOLUTED OR MESH CYLINDER (2) DEEP DISH STEERING WHEEL (7) OTHER: (8) NOT COLLECTED (9) UNKNOWN IF EQUIPPED	<u>8</u>
SWING-AWAY FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	<u>O</u>	ORIGINAL DIMENSION (mm) A: DAMAGE DIMENSION (mm) B: DIFFERENCE (mm)	
TELESCOPING FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	<u>Ø</u>	A - B (888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO MEASURE (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8 22

		STEERING WHEEL AND COLUMN	SC-2
STEERING COLUMN		STEERING WHEEL (CONTINUED)	
ENERGY ABSORBING DEVICE			
TYPE OF DEVICE * (IF 27 OR 28)		STEERING WHEEL HUB DAMAGE	
(00) NOT EQUIPPED (88) NOT COLLECTED (99) UNKNOWN	8 8 24	(0) NONE (1) OCCUPANT CONTACT (2) AIRBAG	<u>©</u>
ORIGINAL LENGTH (mm)		(3) OTHER (9) UNKNOWN	
C:			
COMPRESSED LENGTH (mm)			<u></u>
D:			
BRACKET DEFLECTION (IF CODE 36, 48, OR 49 ABOVE)			
COMPRESSION (OR EXTRUSION) (mm)			
C - D (OR E) (TOLERANCE: ±10)			
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION	8 8 8		
(992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	25 27		
* (ADD A & B FOR TOTAL COMPRESSION)			
SHEAR CAPSULE SEPARATION (mm)			
S (USE AVG. OF LEFT & RIGHT CAPSULES.)			
LT:			
RT:			
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT SEPARATION (992) SEPARATED, AMOUNT UNKNOWN (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8		
COLUMN VERTICAL ROTATION			
(0) NO APPARENT ROTATION (1) UPWARD APPARENT ROTATION (2) DOWNWARD APPARENT ROTATION (9) UNKNOWN	<u>O</u> 31		
COLUMN LATERAL ROTATION			
(0) NO APPARENT ROTATION (1) LEFT APPARENT ROTATION (2) RIGHT APPARENT ROTATION (9) UNKNOWN	<u>O</u> 32		

								INTR	USIO	N IT-1	
Location	of			(All Measurements Are in Centimeters) Comparison Dominant							
Location of Intrusion	n	Intruded Compo		Compar Valu	e -	Intruded Value	=	Intrusion		Crush Direction	
					_		=				
				ļ			=				
			·····				=				
	·		······································				=				
							=				
							=				
							=				
			 				=				
							=				
							=				
					_		=				
							=				
							=				
							=				
							=				
				-			=				
	Т		0	CCUPANT C	ONTACT	WORKSHE	ET				
Contact	Interior Occupant Component No. if Contacted Known		Body Region if Known		Supporting Physical Evidence			Confidence Level of Contact Point			
Α											
В											
С											
D											
Ε											
F											
G											
Н											
<u> </u>											
J		l									

VEHICLE OCCUPANT CONTACT DIAGRAM





DE BELT: LOW ADJUST ON
B-111(AT


BUT EUIDANCE: COURT OUES

B-FILLAT IS CHACKED

GREY PLASTIC TRANSFECS

ON BELT WEBBING FROM

PLASTIC CUIDE ON B-PILLAC



INTRUSION IT-3

CODES FOR COLUMN B, OCCUPANT SPACE NUMBER

OCCUPANT SPACE NUMBER IS A TWO-DIGIT CODE. THE USE OF THE CODE IS DETERMINED BY THE VEHICLE SEAT CONFIGURATION AT THE TIME OF THE ACCIDENT.

FIRST DIGIT

THE FIRST DIGIT (LEFT DIGIT) DENOTES THE SEAT ROW, WITH CODE VALUES FROM 1 TO 5.

SECOND DIGIT

THE SECOND DIGIT (RIGHT DIGIT) DENOTES THE POSITION ON THE SEAT AND, IN SOME INSTANCES, THE WIDTH OF THE SEAT.

(1) LEFT	(3) RIGHT		. INDIVIDUAL SEAT
(1) LEFT	(2) CENTER	(3) RIGHT	BENCH: FULL WIDTH 3 PASSENGER
(1) LEFT	(2) LEFT CENTER	(6) RIGHT (3) RIGHT	BENCH: FULL WIDTH 4 PASSENGER
(1) LEFT	(2) CENTER	(5) RIGHT &	BENCH: PARTIAL WIDTH, LEFT
(0) LEFT & SPACE	(2) CENTER	(5) RIGHT &SPACE	BENCH: PARTIAL WIDTH, CENTERED
(4) ENTIRE	/EHICLE WIDTH		CARGO AREA

EXAMPLES

THE TWO FIGURES BELOW PROVIDE EXAMPLES OF THE OCCUPANT SPACE NUMBER.

PASSENGER CAR 5 PASSENGERS

VAN 12 PASSENGER CAPACITY

X			X	11			13	
x	X	X				21	22	25
x							32	35
X	X	X	X	41	42	46	43	

CODES FOR COLUMN F, MEASUREMENT AXIS

(X) X-AXIS (FORE & AFT)

(Y) Y-AXIS (LATERAL)

(Z) Z-AXIS (VERTICAL)

CODES FOR COLUMNS G, H, I & J, OCCUPANT & INJURY NUMBERS

OCCUPANT NUMBER	INJURY NUMBER	CONTACT
(00)	(00)	NO CONTACT
(##)	(00)	CONTACT, NO INJURY
(97) (99)	(99) (00) OR (99)	CONTACT, OCCUPANT UNKNOWN, INJURY UNKNOWN UNKNOWN IF CONTACT

CODES FOR COLUMN C, INTRUDING COMPONENT OR OBJECT

NOTE: DO NOT CODE OBJECTS OTHER THAN COMPONENTS OF CASE VEHICLE.

INDIVIDUAL COMPONENT

INTERNAL

- (01) INSTRUMENT PANEL
- (02) FIRE WALL
- (03) TOE PAN
- (04) FLOOR PAN
- (05) STEERING COLUMN
- (06) WINDSHIELD
- (07) WINDSHIELD HEADER
- (08) A-PILLAR
- (09) DOOR PANEL OR SIDE PANEL
- (10) WINDOW FRAME
- (11) B-PILLAR
- (12) C-PILLAR
- (13) D-PILLAR
- (14) ROOF SIDE RAILS
- (15) ROOF OR CONVERTIBLE TOP
- (16) BACKLIGHT HEADER
- (17) FRONT SEAT-BACK SURFACE/ SEAT-BACK BACK SURFACE
- (18) SECOND SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (19) THIRD SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (20) FOURTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (21) FIFTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (22) BACK PANEL/BACK DOOR SURFACE
- (23) SEAT CUSHION SURFACE/EDGE
- (24) CONSOLE
- (25) OTHER (DESCRIBE)
- (26) UNKNOWN INTERNAL SURFACES
- (28) TRANSMISSION TUNNEL (HUMP)
- (29) SIDE FOOTWELL PANEL (KICKPANEL)
- (30) SILL

EXTERNAL

- (43) HOOD
- (44) OBJECT EXTERNAL TO PASSENGER COMPARTMENT BUT PART OF CASE VEHICLE
- (45) OUTSIDE SURFACE OF CASE VEHICLE (46) OTHER (E.G. SPARE TIRE,
- (46) OTHER (E.G. SPARE TIRE JACK. DESCRIBE.)
- (49) UNKNOWN EXTERNAL OBJECT

GROUPED FOR MASSIVE INTRUSION INTO AN OCCUPANT SPACE

USE ONLY IF <u>ALL</u> THESE COMPONENTS INTRUDED INTO A SINGLE OCCUPANT SPACE.

- (50)WINDSHIELD HEADER A-PILLAR ROOF SIDE RAIL
- (51)INSTRUMENT PANEL A-PILLAR DOOR PANEL
- (52)INSTRUMENT PANEL A-PILLAR WINDSHIELD HEADER
- (53)DOOR PANEL B-PILLAR ROOF RAIL
- (54)DOOR PANEL A-PILLAR ROOF RAIL
- (55)INSTRUMENT PANEL FLOOR PAN A-PILLAR DOOR FRAME
- (56)ROOF RAIL A-PILLAR B-PILLAR WINDOW FRAME
- (57)ROOF RAIL A-PILLAR B-PILLAR C-PILLAR DOOR PANEL
- (58) ROOF ROOF RAIL WINDOW FRAME DOOR PANEL
- (59)BACKLIGHT HEADER ROOF C-PILLAR THIRD SEAT-BACK

- (60)ROOF
 ROOF RAIL
 A-PILLAR
 B-PILLAR
 C-PILLAR
 WINDOW FRAME
 DOOR PANEL
 FLOOR PAN
- (61)INSTRUMENT PANEL TOE PAN WINDSHIELD HEADER A-PILLAR ROOF RAIL WINDOW FRAME DOOR PANEL ROOF
- (62)ROOF
 ROOF RAIL
 C-PILLAR
 WINDOW FRAME
 FLOOR PAN
 SECOND SEAT
 DOOR PANEL
- (63)ROOF RAIL
 ROOF
 B-PILLAR
 WINDOW FRAME
 FLOOR PAN
 DOOR PANEL
 SECOND SEAT
 FRONT SEAT
- (64)ROOF RAIL
 ROOF OR CONVERTIBLE TOP
 A-PILLAR
 B-PILLAR
 WINDOW FRAME
 WINDOW HEADER
- (65)WINDSHIELD WINDSHIELD HEADER ROOF SIDE RAIL
- (66)WINDSHIELD WINDSHIELD HEADER A-PILLAR
- (98)NOT APPLICABLE
- (99)UNKNOWN

Duplicate columns 1-8 Module from the previous card.	<u>I</u> T Format 0 1 11 12		ln	ITRUSION	IT-5
WAS THERE OCCUPANT COM (0) NO <u>DO NOT</u> ANSWER NEXT QUES (9) UNKNOWN <u>SKIP PAGE</u> .	T QUESTION. <u>SKIP PAGE</u> .	<u>Ø</u>	/AS INTRUSION CAT (0) NO <u>COMPLETE</u> (1) YES <u>SKIP</u> PAGE	PAGE.	14
Duplicate columns 1-8 Module from the previous card. NOTE: Each line in the table below	$\frac{1}{9} \frac{T}{10} \text{Format } \frac{0}{11} \frac{2}{12}$ is a separate record (card). Dup	licate columns	s 1 - 12 for each complete	ed line.	
CODES I	TRUSIONS IN THIS ORDER: LEF FOR B, F, G, H, I, J ON PAGE IT FOR C ON PAGE IT-4		ON ROW; FRONT TO B		ES.
A B C INTRUDING INTRUSION OCC. COMPONENT NUMBER SPACE NO. OR OBJECT		G MAXIMUM INTRUSION Z AXIS (cm)	H I OCCUPANT INJURY NUMBER NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER
13-14 15-16 17-18	19 20-21 22-23	24-25	26-27 28-29	30-31	32-33
0 1					
02					
0 3				_	
0 4				-	
0 5				-	
0 6					
0 7 NOTE: USE ADDITIONAL PAGE IF MORE TH	AN 7 INTRUSIONS.			-	——
_ Duplicate columns 1-8 Module from the previous card.	I T Format 0 3 11 12				
NOTE: IF NO SIDE DOOR INTRUSION, SKIP REMAINDER OF PAGE. SIDE DOOR INTRUSION RESULTED FROM	DOOR INTRUSI	DOOR CO ON, CODE DAMAGED MPONENT 1	MPONENT RESUL COMPONENT DAMAGED COMPONENT 2	TED IN INCRE	EASED
INTRUSION NUMBER CAUSE			_	FOR COMPONE	ENTS
CODES FOR CAUSE:	A 22 23		25	(0) NONE (1) A-PILLAR	
13 15 (1) DIRECT	B		29	(2) B-PILLAR (3) C-PILLAR (4) LATCH/STR	IKER
16 18 (2) INDUCED DAMAGE	C		33	(5) HINGES (7) OTHER:	_
19 21 (9) UNKNOWN	D	-	37	(8) NOT APPLI (9) UNKNOWN	CABLE

Duplicate columns 1-8 from the previous card.

INTRUSION

IT-6

NOTE: Each line in the table below is a separate record (card). Duplicate columns 1 - 12 for each completed line.

- ADDITIONAL PAGE -

INTRUSIONS CODE INTRUSIONS IN THIS ORDER: LEFT TO RIGHT ON ROW; FRONT TO BACK IN VEHICLES. CODES FOR B, F, G, H, I, J ON PAGE IT-3 CODES FOR C ON PAGE IT-4 OCCUPANT CONTACT AND INJURY

CODES FOR C ON PAGE 11-4							OCCUPAN	II CONTACT	AND INJURY	
A INTRUSION NUMBER	B OCC. SPACE NO.	C INTRUDING COMPONENT OR OBJECT	D ASSOC. EVENT NO.	E MAXIMUM INTRUSION X AXIS (cm)	F MAXIMUM INTRUSION Y AXIS (cm)		H OCCUPANT NUMBER	I INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER
13-14	15-16	17-18	19	20-21	22-23	24-25	26-27	28-29	30-31	32-33
0 8										
0 9										
1 0										
1 1										
1 2										
1 3			_					<u> </u>		
1 4				.						
<u>1</u> <u>5</u>										
<u>1</u> <u>6</u>			_							
1 7										
1 8										
1 9										
2 0										
2 1										
2 2										
2 3									——	
2 4			_							
<u>2</u> <u>5</u>			_							


Duplicate columns 1-8 from the previous card.	Modu	lle <u>I</u> <u>D</u>	Format 0 1	ln	TERIOR DAMAGE I	D-1
CO	(1	O) NO I) YES B) NO, and	d OCCUPANT CONTACT	(4) YES, and (8) NOT APPL (9) UNKNOW!	DCCUPANT CONTACT ICABLE N	
SIDES FRONT DOOR FRONT HARDWARE FRONT ARMREST FRONT GLASS REAR DOOR AREA REAR HARDWARE REAR ARMREST REAR GLASS ROOF SIDE RAIL B-PILLAR COUCE (CACCELL) C-PILLAR D-PILLAR HEADLINING - ROOF STRUCTURE T-ROOF/SUN ROOF OTHER: *	LEFT O 13 O 15 O 17 O 19 O 12	RE 0 4 0 5 0 5 0 8 0 8 0 8 0 8 0 8 0 8 0 8 0 8	FRONT FOOT CONTROLS IGNITION KEYS REAR VIEW MIRROR SUNVISOR/FITTINGS (5) LEFT SIDE ONLY (6) RIGHT SIDE ONLY (7) BOTH SIDES WINDSHIELD TOP MOLDINGS LEFT A-PILLAR (UPPER OR LOWER) RIGHT A-PILLAR (UPPER OR LOWER) CENTER CONSOLE TRANSMISSION SELECTOR LEVER RIM, HORN, SPOKE	O 4 O 4 O 4 O 5 O 5 O 5 O 5 O 5	INSTRUMENT PANEL UPPER PANEL MID PANEL LOWER PANEL ASHTRAY CONTROL KNOBS & LEVERS GLOVE COMPARTMENT AREA INSTRUMENTS PARKING BRAKE RELEASE PARKING BRAKE PEDAL A/C OR UPPER VENT OUTLETS HEATER OR A/C DUCTS RADIO OTHER: * THE CONSOLES VERTICAL	64 O 65 O 66 O 69
					VERTICAL	70

^{*} MORE THAN ONE ITEM MAY BE NOTED.

Duplicate columns 1-8 from the previous card. Module S T 10			SEATS		ST-1
FRONT SEAT TYPE OF FRONT SEAT (00) NO SEAT (01) STANDARD BENCH (02) SPLIT BACK, 50-50 (03) SPLIT BACK, DRIVER WIDE (04) SPLIT BACK, PASS. WIDE (05) BUCKET (06) CAPTAIN'S CHAIR (07) INDIV. BENCH, 50-50 (08) INDIV. BENCH, DRIVER WIDE	DRIVER	PASSENTR D 15 16	FRONT SEAT-BACK SEAT-BACK TYPE (1) FORWARD FOLDING (2) RIGID (3) RECLINING (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	DRIVER 3 30	PASSENTI 31
(09) INDIV. BENCH, PASS. WIDE (97) OTHER: (99) UNKNOWN TYPE OF SEAT MOUNT (1) STANDARD (2) PEDESTAL (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	17	18	SEAT-BACK LOCK TYPE (0) NONE (1) MANUAL (2) INERTIA (3) POWER (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	32	1 33
SWIVEL MECHANISM EQUIPPED (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	19	<u>O</u> 20	LOCKS HELD (0) NO (1) YES (8) NOT APPLICABLE	34	35
ORIGINAL EQUIPMENT SEATS (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	21	22	(9) UNKNOWN RECLINER MECHANISM HELD (0) NO	1	1
CONTACT OF SEAT BY REAR OCCUPANT (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>8</u>		(1) YES (8) NOT APPLICABLE (9) UNKNOWN	36	37
FRONT SEAT DAMAGE (0) NONE (1) BACKREST ONLY DAMAGED (2) CUSHION ONLY DAMAGED (3) BACKREST & CUSHION DAMAGED (8) NOT APPLICABLE (9) UNKNOWN	<u>C</u>		HEAD RESTRAINT HEAD RESTRAINT TYPE (0) NONE (1) ADJUSTABLE (2) INTEGRAL (3) NOT INTEGRAL, BUT CANNOT BE REMOVED (7) OTHER: (8) NOT APPLICABLE	<u>Z</u>	<u>Z</u>
CENTER ARMREST DAMAGED (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	ON SERT (2	(9) UNKNOWN REMOVED PRE-CRASH (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	40	<u>S</u>
FRONT SEAT ROTATION (0) NONE APPARENT (1) FORWARD APPARENT (2) REARWARD APPARENT (3) LEFT APPARENT (4) RIGHT APPARENT (5) MULTIPLE ROTATIONS SPECIFY (8) NOT APPLICABLE	28	<u>Ø</u>	ADJUSTMENT AT CRASH (1) UP (2) DOWN (8) NOT APPLICABLE (9) UNKNOWN HEAD RESTRAINT DAMAGE (0) NONE (1) DAMAGED BUT NOT SEPARATED (2) SEPARATED (8) NOT APPLICABLE (9) UNKNOWN	امل 42 الإ	8 43 0 45

			Se	EATS S	ST-2
FRONT SEAT ADJUSTMENT	DRIVER	Passen'r	SECOND SEAT (CONT.)		
SEAT ADJUSTMENT TYPE (0) NONE (RIGID) (1) MANUAL (2) POWER (7) OTHER: (8) NOT APPLICABLE (NO SEAT) (9) UNKNOWN ADJUSTMENT PROVIDED (1) 2-WAY	46	47	CENTER ARMREST DAMAGED (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	6	8
(2) 4-WAY (3) 6-WAY (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	48	49	SECOND SEAT-BACK LOCKS	LEFT	Rі <mark>с</mark> нт
SEAT ADJUSTER DAMAGE (0) NONE (1) CHUCKING (FREE PLAY) (2) DEFORMED (RELEASED/JAMMED) (3) SEPARATED (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	50	<u>6</u>	FOR THE FOLLOWING, USE: (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN		
SEAT ADJUSTER SEPARATION (0) NONE (1) SEPARATED AT FLOOR (2) SEPARATION OF ADJUSTER (3) SEPARATED AT SEAT (8) NOT APPLICABLE (9) UNKNOWN	52	<u>&</u>	LEFT OR CENTER, EQUIPPED LEFT OR CENTER, HELD (3) SEAT FOLDED DOWN RIGHT, EQUIPPED	63	Q ₈ 86 ₄ +8
PRE-CRASH POSITION (1) FORWARD (2) MIDDLE (3) REARWARD (8) NOT APPLICABLE (9) UNKNOWN	<u>3</u>	3 55	RIGHT, HELD (3) SEAT FOLDED DOWN THIRD SEAT	0 8 6 6	68
SECOND SEAT TYPE OF SECOND SEAT (0) NONE (1) NON-FOLDING	LEFT	Right	EQUIPPED BACKREST DAMAGED		021021
(2) FOLDING (3) CAPTAIN'S CHAIR (4) JUMP SEAT (5) INTEGRAL CHILD SEAT (6) LUGGAGE AREA ACCESS PANEL (9) UNKNOWN	2 56	57	VEHICLE EQUIPPED WITH	73	74
SECOND SEAT DAMAGE (0) NONE (1) BACKREST ONLY (DAMAGED OR LOOSENED) (2) CUSHION ONLY (DAMAGED OR LOOSENED) (3) BACKREST & CUSHION (DAMAGED OR LOOSENED) (4) INTEGRAL CHILD SEAT (PRIORITY CODE) (5) LUGGAGE AREA ACCESS PANEL (DAMAGED OR LOOSENED) (8) NOT APPLICABLE (9) UNKNOWN	<u>O</u>) 58	<u>O</u> 59	(0) NOT EQUIPPED (OR REMOVED) (1) EQUIPPED (2) EQUIPPED & DAMAGED (8) NOT APPLICABLE (NO REAR SEAT) (9) UNKNOWN Applies to any rear-seat position	7:	Ø

Duplicate columns 1-8 Module A B Format C from the previous card.	<u>1</u> 1 12	AIRBAG	AB-1
DRIVER SIDE LOCATION OF AIRBAG STEERING WHEEL EQUIPPED (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED	13	PASSENGER SIDE LOCATION OF AIRBAG INSTRUMENT PANEL (GLOVE BOX) EQUIPPED (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED	16
DEPLOYED (0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	14	DEPLOYED (0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	17
CONDITION OF AIRBAG STEERING WHEEL (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (MOT EQUIPPEDMOT DEPLOYED) (9) UNKNOWN IF EQUIPPED OR CONDITION		CONDITION OF AIRBAG INSTRUMENT PANEL (GLOVE BOX) (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPED/NOT DEPLOYED) (9) UNKNOWN IF EQUIPPED OR CONDITION	<u>D</u> 18
DRIVER SIDE AIRBAG STEERING WHEEL TETHER (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	19	PASSENGER SIDE AIRBAG INSTRUMENT PANEL (GLOVE BOX) TETHER (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	<u>O</u> 21
MARKED BY CONTACT (0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	20	MARKED BY CONTACT (0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	



NOTE TO THE INVESTIGATOR:

THE FOLLOWING TWO SECTIONS,

OCCUPANT INFORMATION AND INJURY CLASSIFICATION,

ARE TO BE FILLED IN

FOR EACH CASE VEHICLE OCCUPANT,

WHETHER INJURED OR NOT.

IF THERE IS MORE THAN ONE OCCUPANT,
USE ADDITIONAL COPIES
OF PAGES OC-1, OC-2, OC-3,
AND IC-2 TO DESCRIBE THEM
AND ATTACH THE COPIES TO THIS REPORT.


Duplicate columns 1-8 from the previous card. Module O C Format 0 11	12	OCCUPANT INFORMATION	OC-1
OCCUPANT IDENTIFICATION OCCUPANT NUMBER ROLE OF OCCUPANT AT 1ST IMPACT (1) MOTOR VEHICLE DRIVER (2) MOTOR VEHICLE PASSENGER (NOT DRIVER) (9) UNKNOWN	O 1 13 14	PHYSICAL DESCRIPTION AGE IN YEARS (00) LESS THAN 1 YEAR (98) 98 YEARS OR OLDER (99) UNKNOWN AGE IN MONTHS (00) LESS THAN 1 MONTH (25) 25 MONTHS OR OLDER (99) UNKNOWN	$\frac{28}{20}$ $\frac{2}{21}$ $\frac{25}{22}$ $\frac{5}{23}$
OCCUPANT POSITION ROW LOCATION (1) FRONT (2) SECOND (3) THIRD (4) FOURTH (7) OTHER: (8) EXTERNAL TO PASSENGER COMPARTMENT (E.G. BED OF PICKUP) (9) UNKNOWN	16	MASS (kg) (999) UNKNOWN HEIGHT (cm) (999) UNKNOWN SEX (1) MALE (2) FEMALE (9) UNKNOWN	173 27 28 29 27 30
LATERAL LOCATION (1) LEFT (2) LEFT CENTER (3) CENTER (4) RIGHT CENTER (5) RIGHT (6) ALL (LYING ON SEAT) (8) EXTERNAL TO PASSENGER COMPARTMENT (9) UNKNOWN	17	MEDICAL CONDITIONS TREATMENT/MORTALITY (00) NONE (01) FIRST AID AT SCENE (02) TREATED AT HOSPITAL/CLINIC BUT NOT ADMITTED (03) HOSPITALIZED FOR OBSERVATION LESS THAN 24 HOURS (04) HOSPITALIZED OVER 24 HOURS OR FOR SIGNIFICANT TREATMENT (05) FATAL, DEAD AT SCENE (06) FATAL, DOA	<u>0</u> <u>4</u> 31 32
POSTURE (10) SITTING ON SEAT (11) SITTING ON SEAT IN ABNORMAL POSITION (E.G. FEET ON DASH, SIDEWAYS) (12) SITTING ON CONSOLE (20) ON LAP OR IN ARMS (30) STANDING ON SEAT (40) STANDING ON FLOOR (47) STANDING, EXTERNAL TO PASSENGER COMPARTMENT (50) IN BASSINET (60) IN CHILD SEAT (65) IN CHILD HARNESS (70) LYING ON SEAT (80) LYING/SITTING ON PASSENGER FLOOR (83) LYING/SITTING ON OTHER OBJECT IN PASSENGER COMPARTMENT: (85) ON CARGO FLOOR/FOLDED SEAT-BACK	18 19	(07) FATAL, DEAD WITHIN 24 HOURS (08) FATAL, DEAD 24 HOURS TO 31 DAYS LATER (09) FATAL, DEAD 31 DAYS TO 1 YEAR LATER (10) FATAL DEAD WITHIN UNKNOWN PERIOD (99) UNKNOWN INJURY SEVERITY SCORE (ISS) (99) UNKNOWN NON-IMPACT MED. CONDITIONS (0) NONE (1) YES, TIME & TYPE UNKNOWN (2) PRE-CRASH FATAL (CLINICAL DEATH AT WHEEL) (3) PRE-CRASH NON-FATAL (E.G. PRIOR INJURY, STROKE) (4) PREGNANT (5) POST-CRASH NON-FATAL (DROWNING)	35 30 Wee

		OCCUPANT INFORMATION	OC-2
MEDICAL CONDITIONS (CONT.) POLICE INJURY SEVERITY CODE FOR THIS OCCUPANT (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO IMPACT (7) NON-FATAL INJURY, SEVERITY UNKNOWN (9) UNKNOWN		CHILD SEAT TYPE (00) NONE USED (01) YES, USED (02) INTEGRAL, Chrysler Mini-van (88) NOT APPLICABLE (ADULT OR OLDER CHILD) (99) UNKNOWN CHILD SEAT MAKE/MODEL	8 8 41 42
RESTRAINT SYSTEM			
(0) NONE (1) LAP BELT (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (9) UNKNOWN ACTIVE RESTRAINT SYSTEM USAGE (0) NONE (AVAILABLE BUT NOT USED) (1) LAP BELT ONLY (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (7) IMPROPER USAGE (8) NOT APPLICABLE (NONE AVAILABLE) (9) UNKNOWN PASSIVE RESTRAINT SYSTEM (0) NONE (1) AIRBAG INSTALLED (2) PASSIVE UPPER TORSO WITH KNEE BOLSTERS (3) PASSIVE UPPER TORSO WITHOUT KNEE BOLSTERS (4) PASSIVE LAP & UPPER TORSO (5) AIRBAG INSTALLED & PASSIVE RESTRAINT (7) OTHER: (9) UNKNOWN	3 37 38	EJECTION DEGREE OF EJECTION (0) NONE (1) PARTIAL (2) COMPLETE (7) EJECTED, DEGREE UNKNOWN (9) UNKNOWN IF EJECTED AREA OF EJECTION (01) WINDOW, LEFT SIDE (02) WINDOW, RIGHT SIDE (03) WINDOW, REAR (04) DOOR, LEFT SIDE (05) DOOR, RIGHT SIDE (06) DOOR, REAR OR TAILGATE (07) WINDSHIELD (08) ROOF OR OPEN CONVERTIBLE OR FROM EXTERNAL AREA (96) EJECTED AREA UNKNOWN (97) OTHER AREA: (98) NOT APPLICABLE (NOT EJECTED) (99) UNKNOWN IF EJECTED	9844
(0) SYSTEM DEFEATED (1) AIRBAG NOT DEPLOYED (2) AIRBAG DEPLOYED (3) AIRBAG NOT REINSTALLED (4) PASSIVE UPPER TORSO USED (5) PASSIVE LAP & UPPER TORSO USED (6) SYSTEM USED IN MANUAL MODE (7) IMPROPER USAGE (8) NOT APPLICABLE (NOT ORIGINALLY EQUIPPED) (9) UNKNOWN	<u>2</u>	HEAD RESTRAINT HEAD RESTRAINT AVAILABLE FOR THIS POSITION (0) NOT EQUIPPED OR REMOVED (1) EQUIPPED (9) UNKNOWN	46


		OCCUPANT INFORMATION	OC-3
OCCUPANT EYEWEAR (0) NONE (1) GLASSES (2) CONTACTS (3) BOTH GLASSES AND CONTACTS (4) OTHER (8) NOT APPLICABLE (9) UNKNOWN	1/47	SOURCE OF INFORMATION (0) INTERVIEW (1) HOSPITAL (2) AUTOPSY (3) POLICE (4) OTHER (5) LAY CORONER/EXTERNAL EXAM (7) COMBINATION OF ABOVE (CIRCLE) (8) NOT APPLICABLE (9) UNKNOWN	Z

OCCUPANT INFORMATION OC-4

INDICATE LOCATION OF INJURIES.



No Injury



Duplicate columns 1-8 from the previous card.

Module <u>I</u> <u>C</u> Format <u>0</u> <u>1</u> 12

Injury Classification IC-1

NOTE: Each line in the table below is a separate record (card).

Duplicate columns 1 - 12 for each completed line.


OCCUPANT INJURY CLASSIFICATION

							PRIM	IARY	OIC		А	ssoc	IATE	OIC		COMMENTS
OCCUPANT NUMBER	INJURY NUMBER	PLACE CONTACTS IN ORDER OF PROBABILITY (HORIZONTALLY) . START WITH MOST PROBABLE IN 1ST CONTACT AREA COLUMN. AREA(S) OF POSSIBLE CONTACT 1ST 2ND			BODY REGION 1	ASPECT O	LESION 3	SYSTEM/ORGAN 4	SEVERITY 15	BODY REGION 1	ASPECT N	LESION 3	SYSTEM/ORGAN 4	SEVERITY 15		
13-14	15-16	17-18	19-20	СОММЕ	NTS	21	22	23	24	25	26	27	28	29	30	
01				NO	INJ	UR	7	_	_	-	_	_	_	_		
						-	_	_	_	-	_	_	_	_	-	
						_	_	_	_	_	_	_		_	-	
						_	_	_		-	_	_	_	_	-	
						_	_		_	_	_	_			_	
						_	_		_	-	_	_	_	_	-	
							_		_	_	_	_		_	-	
ei							_		_	-	_	_		_	_	
e "Occupant Number" for each line.						_	_	_	_	-	_	_		_	_	
umber" f						_	_	_	_	-	_	_		_	-	
cupant N						_	_		_	-	_	_	_	_	-	
cate "Oc						_	_	_	_	-	_	_		_	_	
- Duplicat							_	_	_	-	_	_	_	_	-	
						_	_	_		-	_		_	_	-	
						4	_	_	_	-	_			_	_	
							_	_	_	-	_	_	_	_	-	
							_	_	_	-	_	_	_	_	_	
							_		_		_	_				

INJURY CLASSIFICATION IC-2

CODES FOR AREAS OF POSSIBLE OCCUPANT CONTACT

FRONT	OF PASSENGER COMPARTMENT	SIDES	
(10)	SUNVISOR, FITTING(S) &/OR TOP MOLDING	(20)	SURFACE OF SIDE INTERIOR
(12)	WINDSHIELD	(19)	HARDWARE ON SIDE OR DOOR
		(13)	
(05)	INSTRUMENT PANEL (SPECIFIC AREA UNKNOWN)	(24)	
(54)	UPPER INSTRUMENT PANEL (X)	(- ·	
(55)	MIDDLE INSTRUMENT PANEL (Y)	(22)	WINDOW GLASS (SIDE)
(56)	LOWER INSTRUMENT PANEL (Z)	(21)	• •
(81)	ASH TRAY (INSTRUMENT PANEL)	(21)	WINDOW FRAMES (SIDE)
(02)	GLOVE COMPARTMENT AREA	(06)	DOOF SIDE DAIL
(47)	AIRBAG (ACRS) COMPARTMENT DOOR/COVER	(26)	
(47)	AIRDAG (ACAS) COMPARTMENT DOCACOVER	(14)	
(57)	DENICATE UNICEDI INCRIT DANICI	(15)	
(57)	BENEATH INSTRUMENT PANEL	(16)	
(53)	PARCEL TRAY	(17)	D-PILLAR
(48)	KNEE RESTRAINT	_	
(86)	VERTICAL CONSOLE	FLOOR	
		(40)	FLOOR
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(27)	CONSOLE ON FLOOR OR BETWEEN SEATS
		(44)	TRANSMISSION LEVER ON FLOOR OR CONSOLE
(09)	STEERING ASSEMBLY (SPECIFIC AREA UNKNOWN)	(85)	
(65)	STEERING WHEEL	(28)	
(66)	STEERING WHEEL COLUMN	(91)	· (
(59)	TRANSMISSION LEVER ON COLUMN	(-,	
(,		Roof	
(03)	HARDWARE ITEM (SPECIFIC AREA UNKNOWN)	(25)	ROOF OR CONVERTIBLE TOP
(82)	INSTRUMENT(S)		
(83)	CONTROL KNOB(S) & LEVER(S) (FRONT)	(10)	
		(26)	
(84)	PARKING BRAKE HANDLE IN FRONT	(24)	
(67)	IGNITION KEY	(18)	
(06)	MIRROR	(39)	· ·
(04)	HEATER OR AIR CONDITIONING DUCTS	(68)	ROOF MOUNTED CONTROLS/CONSOLE
(01)	AIR CONDITIONING OR VENTILATION OUTLET(S)	(69)	ROLL BAR
(08)	RADIO (BUILT IN)		
(58)	ADD-ON TAPE DECK, RADIO, A/C	EXTERIO	OR SURFACE OF CASE VEHICLE
(68)	ROOF MOUNTED CONTROLS/CONSOLES	(37)	OUTSIDE SURFACE OF CASE VEHICLE
		` '	(SPECIFIC AREA UNKNOWN)
REAR		(35)	HOOD OF CASE VEHICLE
(88)	SURFACE OF REAR INTERIOR	(60)	EXTERIOR OF CASE VEHICLE (E.G.
	REAR WINDOW	(00)	OUTSIDE MIRRORS, ANTENNA, TRIM)
	REAR WINDOW HEADER	(62)	EXTERIOR SIDE ROOF RAIL OF CASE VEHICLE
(50)	REAR SEAT CUSHION & BACK		
(30)	NEAR SEAT COSTITION & BACK	(63)	TRUNK LID OF CASE VEHICLE
INTEDIO	R-GENERAL	(64)	TIRES OF CASE VEHICLE
		Provin	Cass Value a Bernara
	TRANSMISSION SELECTION LEVER (LOCATION UNK.)		CASE VEHICLE BOUNDARY
(59)	TRANSMISSION LEVER ON STEERING COLUMN		AREA EXTERIOR TO CAR (SPECIFIC AREA UNK.)
(44)	TRANSMISSION LEVER ON FLOOR OR CONSOLE	(70)	HOOD OF OTHER VEHICLE
	PARKING BRAKE HANDLE (LOCATION UNKNOWN)	(71)	OTHER VEHICLE EXTERIOR HARDWARE (E.G.
(84)	PARKING BRAKE HANDLE IN FRONT		OUTSIDE MIRRORS, ANTENNA, TRIM)
(85)	PARKING BRAKE HANDLE ON FLOOR OR CONSOLE	(73)	EXTERIOR SIDE ROOF RAIL OF OTHER VEHICLE
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(74)	HEADLIGHT OR FRONT GRILL OF OTHER VEH.
		(75)	TRUNK OF OTHER VEHICLE
(29)	FRONT SEAT-BACK(S)	(76)	OUTSIDE SURFACE OF OTHER VEHICLE
(51)	FRONT SEAT CUSHION	(77)	TIRES OF OTHER VEHICLE
(50)	REAR SEAT CUSHION & BACK	(78)	GROUND
	ARMREST ON SEAT	(79)	WATER
(89)	UNDER SEAT BOTTOM	i i	
(03)	ONDER OEAT SOTTOM	(80)	EXTERIOR OBJECT (NOT VEHICLE, GROUND,
(33)	RESTRAINT SYSTEM HARDWARE		OR WATER. PLEASE DESCRIBE.)
		Dever	
	RESTRAINT SYSTEM WEBBING		ATING OBJECTS
(87)	AIR CUSHION SKIN (AIRBAG)		OTHER VEHICLE
(47)	AIRBAG (ACRS) COMPARTMENT DOOR/COVER	(72)	OBJECTS (DESCRIBE)
(46)	AIRBAG GAS		
(48)	KNEE RESTRAINT	MISCELL	
(30)	HEAD RESTRAINT	(00)	NO CONTACT (INVALID FIELD FORM CODE)
(42)	CHILD SEAT RESTRAINTS	(38)	OTHER (E.G. FIRE. DESCRIBE)
	CHILD SEAT	(90)	SPARE TIRE
	INTERIOR LOOSE OBJECT	(96)	INDUCED
(32)	OTHER OCCUPANT(S)	(97)	EJECTED, UNKNOWN CONTACT
(52)	INTERNAL FLYING GLASS (FROM ANY SOURCE)	(98)	IMPACT FORCE, "WHIPLASH",
	UNKNOWN INTERIOR SURFACE	, ,	HYPEREXTENSION/COMPRESSION
-		(99)	LINKNOWN AREA OF CONTACT



INJURY CLASSIFICATION IC-4

CODES FOR OCCUPANT INJURY CLASSIFICATION (OIC)

-		
- 1	PODV	DECION
	זטטם	REGION

- (H) HEAD/SKULL
- (F) FACE
- (N) NECK
- (S) SHOULDER
- (X) UPPER EXTREMITIES
- (A) ARM (UPPER)
- (E) ELBOW
- (R) FOREARM
- (W) WRIST/HAND
- (C) CHEST
- (M) ABDOMEN
- (B) BACK
- (P) PELVIC/HIP
- (Y) LOWER EXTREMITIES
- (T) THIGH
- (K) KNEE
- (L) LEG (LOWER)
- (Q) ANKLE/FOOT
- (O) WHOLE BODY
- (U) UNKNOWN

3 LESION

- (L) LACERATION
- (C) CONTUSION
- (A) ABRASION
- (F) FRACTURE
- (P) PERFORATION, PUNCTURE
- (K) CONCUSSION
- (V) AVULSION
- (R) RUPTURE
- (S) SPRAIN
- (D) DISLOCATION
- (N) CRUSH
- (M) AMPUTATION
- (B) BURN
- (G) DETACHMENT, SEPARATION
- (Z) FRACTURE AND DISLOCATION
- (T) STRAIN
- (E) TOTAL SEVERANCE, TRANSECTION
- (O) OTHER
- (U) UNKNOWN

4 SYSTEM/ORGAN

- (S) SKELETAL
- (V) VERTEBRAE
- (J) JOINTS
- (D) DIGESTIVE
- (L) LIVER
- (N) NERVOUS SYSTEM
- (B) BRAIN
- (C) SPINAL CORD
- (E) EARS
- (O) EYES
- (A) ARTERIES
- (H) HEART
- (Q) SPLEEN
- (G) UROGENITAL
- (K) KIDNEYS
- (R) RESPIRATORY
- (P) PULMONARY/LUNGS
- (M) MUSCLES
- (T) THYROID, OTHER ENDOCRINE GLAND
- (I) INTEGUMENTARY (SKIN)
- (W) ALL SYSTEMS IN REGION
- (U) UNKNOWN

2 ASPECT

- (R) RIGHT
- (L) LEFT
- (B) BILATERAL
- (C) CENTRAL
- (A) ANTERIOR/FRONT
- (P) POSTERIOR/BACK
- (S) SUPERIOR/UPPER
- (I) INFERIOR/LOWER
- (W) WHOLE REGION
- (U) UNKNOWN

SEVERITY 5 SYSTEM/ORGAN 4 LESION 3 ASPECT 0 BODY REGION 1

5 SEVERITY (OR "AIS", ABBREVIATED INJURY SCALE)

- (0) NONE
- (1) MINOR
- (2) MODERATE
- (3) SERIOUS
- (4) SEVERE
- (5) CRITICAL
- (6) MAXIMUM
- (9) UNKNOWN





speed limit 45 mgh (75 kg/l)















N 18400#1









18400#12



18400 #13



18400#14







18400#17







































est Available



